

Tohoku Murata Manufacturing Co., Ltd.

1-1 Shimosugishita, Takakura, Hiwada-machi,
Koriyama-shi, Fukushima 963-0531 JAPAN

October 4, 2022

Information of Conformity

The RoHS 2 Directive (2011/65/EU, (EU) 2015/863) does not apply to batteries and battery packs (hereafter batteries). The EU Battery Directive (2006/66/EC) applies to batteries.

The products provided by Tohoku Murata Manufacturing Co., Ltd. do not include the following ten restricted substances of RoHS 2.


Tohoku Murata Manufacturing Co., Ltd. informs you not containing ten restricted substances of RoHS 2.

This letter is not prepared for general products but for all the following product

Murata Model name: Please refer to the appendix.

Restricted hazardous substances	Threshold
Lead (Pb)	0.1%
Mercury (Hg)	0.1%
Cadmium (Cd)	0.01%
Hexavalent chromium (Cr(VI))	0.1%
Polybrominated biphenyls (PBB)	0.1%
Polybrominated diphenyl ether (PBDE)	0.1%
Bis (2-ethylhexyl)phthalate (DEHP)	0.1%
Butyl benzyl phthalate (BBP)	0.1%
Dibutyl phthalate (DBP)	0.1%
Diisobutyl phthalate (DIBP)	0.1%

General Manager
Business Unit Quality Assurance Department 3,
Quality Assurance Division



Koshi Kinoshita

Tohoku Murata Manufacturing Co., Ltd.
 1-1 Shimosugishita, Takakura, Hiwada-machi,
 Koriyama-shi, Fukushima 963-0531 JAPAN

Appendix

List of Murata Model Name

SP513641A10	SP603139E1S	SP873440N2Y	SP943043N2S	US253450A10S	US25A2F2H3
US275361H5	US2764A0K6S	US321741A10S	US323450A7H	US372632H2	US373651A10S
US383396K7S	US395189BH7	US3978A4H5K	US404261A10T	US404562H5	US413230H1
US416189H2	US416189H2K	US422024EH9L	US435473H2	US454261A8TS	US454992BH7
US485490H5K	US486588K5S	US491222A10S	US501424A10S	US503759A8H	US505456A10S
US506071H2	US508168H5K	US515375BH7P	US515569H5	US516766BH7P	US523350N2Y
US533144N2S	US534677BH7P	US564897H7P	US595676K5S	US607272AH7P	US613143N2Y
US616484K6S	US623856E1S	US633346E1S	US633450A9H	US634038A10S	US635472H7P
US666588K6S	US674247AH4	US773038A12	US783038E1S	US97500A10S	US422126EM2
US422126GM3	US583548BH7P	US596573EH10	US626672BH9	US682746AH7P	US844565H7K