

**Tohoku Murata Manufacturing Co., Ltd.**  
 1-1 Shimosugishita, Takakura, Hiwada-machi,  
 Koriyama-shi, Fukushima 963-0531 JAPAN

September 3, 2025

## Information of Conformity

The RoHS 2 Directive (2011/65/EU, (EU) 2015/863) does not apply to batteries and battery packs (hereafter batteries). The EU Battery Regulation (2023/1542) Article 6, Annex I applies to batteries.

Tohoku Murata Manufacturing Co., Ltd. informs you not containing ten restricted substances of RoHS 2.

Product Name:

US14430VR1,	US14430VR2,	US14430W3,	US14500V,	US14500V1,
US14500VR2,	US14500VR2B,	US14500FT1,	US18500G6G,	US18500N1E,
US18500VC7,	US18650G6E,	US18650NC1,	US18650V3,	US18650V3B,
US18650VC3,	US18650VC7,	US18650VT1,	US18650VT3,	US18650VT4,
US18650VTC1,	US18650VTC2,	US18650VTC3,	US18650VTC4,	US18650VTC4A,
US18650VTC5,	US18650VTC5A,	US18650VTC5AM,	US18650VTC5D,	US18650VTC6,
US18650FTC1,	US21700VTC6A,	US21700VTC6AF,	US26650FTC1,	US26650FTC1A,
US21700VX40				

Restricted hazardous substances	Threshold
Lead (Pb)	0.1%
Mercury (Hg)	0.1%
Cadmium (Cd)	0.01%
Hexavalent chromium (Cr(VI))	0.1%
Polybrominated biphenyls (PBB)	0.1%
Polybrominated diphenyl ether (PBDE)	0.1%
Bis (2-ethylhexyl)phthalate (DEHP)	0.1%
Butyl benzyl phthalate (BBP)	0.1%
Dibutyl phthalate (DBP)	0.1%
Diisobutyl phthalate (DIBP)	0.1%

General Manager  
 Business Unit Quality Assurance Department 3,  
 Quality Assurance Division



Koshi Kinoshita